



## Inspection Detail

[Click to watch the video](#)



<b>Client:</b>	HDD Broker		
<b>Inspected by:</b>			
<b>Location of Inspection:</b>			
<b>Phone No / Email:</b>			
<b>Date of Inspection:</b>	3/2/2026	<b>Job#:</b>	
<b>Year:</b>	2021	<b>Make:</b>	DW
<b>Model:</b>	JT30AT	<b>VIN/SN:</b>	

### Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

## Inspection Details

### Unit Information

<b>Hours:</b>	5,564	<b>Date:</b>	N/A
---------------	-------	--------------	-----

### General Body

<b>Paint condition:</b>	See Notes	<b>Panel dents:</b>	No	<b>Corrosion:</b>	Yes
<b>Dents/Bends:</b>	No	<b>Visible leaks:</b>	See Notes	<b>Operator console pivot/lock:</b>	No Damages Observed
<b>Operator's Seat:</b>	No Damages Observed	<b>Operator Console Joysticks, switches, gauges:</b>	No Damages Observed	<b>Fresh water tank (if applicable):</b>	No Damages Observed

### Safety Equipment

<b>Operator's presence switch (seat):</b>	No Damages Observed	<b>Safety switches:</b>	No Damages Observed	<b>Red safety bars (rod loader extensions):</b>	N/A
<b>Work lights:</b>	See Notes	<b>Strike alert/ground wire:</b>	No Damages Observed	<b>Safety decals:</b>	See Notes

### Breakout System

<b>Breakout jaw wear:</b>	No Damages Observed	<b>Cylinder and hose condition:</b>	No Damages Observed	<b>Pins/bushings slop:</b>	No Damages Observed
<b>Front Stakedown System:</b>	No Damages Observed	<b>Auger condition:</b>	No Damages Observed		

### Main Drive System

<b>Tracks (steel or rubber):</b>	Rubber	<b>Track condition:</b>	See Notes	<b>Sprockets/rollers:</b>	No Damages Observed
----------------------------------	--------	-------------------------	-----------	---------------------------	---------------------

### Rear Outriggers

<b>Cylinder and hose condition:</b>	No Damages Observed	<b>Pins and bushings:</b>	No Damages Observed	<b>Bent/broken parts:</b>	No
-------------------------------------	---------------------	---------------------------	---------------------	---------------------------	----

### Carriage

<b>Wear pads/carriage slop:</b>	No Damages Observed	<b>Motors and hoses condition:</b>	See Notes	<b>Rack and pinion condition:</b>	No Damages Observed
---------------------------------	---------------------	------------------------------------	-----------	-----------------------------------	---------------------

### Engine Details

<b>Fluid level and condition:</b>	N/A	<b>Visible leaks:</b>	No	<b>Belts and pulleys:</b>	No Damages Observed
<b>Engine mounts:</b>	No Damages Observed	<b>Radiator/hoses:</b>	No Damages Observed		

### Operation

<b>Engine start and idle:</b>	Yes	<b>Engine smoke:</b>	No	<b>Engine noises (tick/knock):</b>	No
<b>Rear outrigger operation:</b>	No Damages Observed	<b>Main rack tilt:</b>	No Damages Observed	<b>Front stakedown rotation/up/down:</b>	No Damages Observed
<b>Breakout vices open/close/rotate:</b>	No Damages Observed	<b>Rod loader lift/shuttle/alignment:</b>	See Notes	<b>Carriage traverse (thrust/pullback):</b>	No Damages Observed
<b>Rotation motor fwd/reverse:</b>	No Damages Observed	<b>Mud pump on/off:</b>	No Damages Observed		

### Drill Rods

<b>Rod count:</b>	30	<b>Bent rods:</b>	No	<b>Thread condition:</b>	No Damages Observed
<b>Corrosion:</b>	Yes				

## Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

## Tracks

<b>Left Track Condition:</b>	No Damages Observed	<b>Left Track Brand:</b>	Obstructed	<b>Left Track Size:</b>	Obstructed
<b>Left Track Tread Depth Measurement:</b>	26/32"	<b>Left Track Rollers:</b>	No Damages Observed		
<b>Right Track Condition:</b>	See Notes	<b>Right Track Brand:</b>	Obstructed	<b>Right Track Size:</b>	Obstructed
<b>Right Track Tread Depth Measurement:</b>	31/32"	<b>Right Track Rollers:</b>	No Damages Observed		

## Observations / Comments

The unit runs and operates.
-----------------------------

### Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

## Wear and Tear Items

Item Name	Item Comments
Decals	The unit has damaged decals and safety stickers.
Right Track	The unit's right track has cuts and gouges in it.
Wet Cylinder	The unit's rear rod reloading and unloading cylinder is wet and leaking, and will need further diagnostics and repairs. Cylinder hoses on the unloading and loading cylinder are wet and leaking, and will need further diagnostics and repairs.
Hydraulic Leak	The unit had wet stains on the asphalt under the unit at the time of inspection and will need further diagnostics.
Front Work Light	The unit's front worklights near the augers were not illuminated during the inspection and will need further diagnostics.
A/C Temp Knob	The A/C temperature knob is missing.
A/C Vents	The unit has damaged A/C vents in the cab and will need repairs.
Rod Thread Lubricant	The unit did not dispense lubricant when the drill rods were assembled in the operation video, and the unit will need further diagnostics and repairs.
Rust	The unit has rust damage all over the unit and its components. The unit's front augers and drill rods all have surface rust.
Paint	The unit has minor paint damage spread across the entire unit.

### Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.